

2016 lead test results

COFFIN SCHOOL

9 TURNER ROAD

SAMPLE LOCATION	first draw Lead level (Pb Final)	30 second flush Lead Level (Pb Final)
kitchen sink BR	4.81 ug/L	2.00ug/L
room 17 bubbler	<1.00 ug/L	<1.00ug/L
room 16 bubbler	4.44 ug/L	2.81ug/L
room 15 bubbler	2.41 ug/L	1.17ug/L
room 14 bubbler	2.31 ug/L	1.74ug/L
HW bubbler rm 16	1.63 ug/L	2.57ug/L
HW bubbler rm 18	2.24 ug/L	1.57ug/L
faculty sink	4.00 ug/L	2.99ug/L
room 18 bubbler	1.41 ug/L	1.48ug/L
room 12 bubbler	3.88 ug/L	1.60ug/L
room 1 sink	2.60 ug/L	1.15ug/L
room 2 sink	3.92 ug/L	1.83uug/L
HW bubbler rm 2	2.98 ug/L	2.52ug/L
HW bubbler rm 5	6.26 ug/L	1.75ug/L
room 5 sink	<1.00 ug/L	1.16ug/L
room 6 sink	2.26 ug/L	2.22ug/L
room 7 sink	10.2 ug/L	2.38ug/L

EPA - DEP ACTION LEVEL 15.5 ug/L

2018 lead test results

COFFIN SCHOOL

9 TURNER ROAD

RE Tested 8/15/2018 10/15/2018*
new fixture Installed

SAMPLE LOCATION	first draw Lead level (Pb Final)	30 second flush Lead Level (Pb Final)	First Draw Lead Level (Pb Final)	30 second flush Lead Level (Pb Final)
kitchen sink BR	76.6 ug/L	8.73 ug/L	1.44 ug/L	<1.00ug/L
room 17 bubbler	4.09 ug/L	<1.0 ug/L		
room 16 bubbler	9 ug/L	2.01 ug/L		
room 15 bubbler	12.2 ug/L	1.21 ug/L		
room 14 bubbler	12.5 ug/L	1.44 ug/L		
HW bubbler rm 16	2.05 ug/L	2.76 ug/L		
HW bubbler rm 18	5.92 ug/L	1.36 ug/L		
faculty sink	23.5 ug/L	1.88 ug/L	6.51 ug/L	4.35ug/L
room 18 bubbler	<1.0 ug/L	1.27 ug/L		
room 12 bubbler	10.3 ug/L	1.71 ug/L		
room 1 sink	2.22 ug/L	1.34 ug/L		
room 2 sink	1.44 ug/L	1.14 ug/L		
HW bubbler rm 2	7.14 ug/L	2.54 ug/L		
HW bubbler rm 5	13.5 ug/L	3.48 ug/L	9ug/L*	2 ug/L*
room 5 sink	1.81 ug/L	1.03 ug/L		
room 6 sink	8.23 ug/L	3.97 ug/L		
room 7 sink	249 ug/L	69.9 ug/L	2 ug/L*	1ug/L*

EPA - DEP ACTION LEVEL 15.5 ug/L