

2016 Test Results

MALCOM BELL (UPPER)

40 BALDWIN RD

New Bubbler Installed

SAMPLE LOCATION	First Draw	30 second flush	First Draw	30 second flush
	Lead Level (Pb Final)	Lead Level (Pb Final)	Lead Level (Pb Final)	Lead Level (Pb Final)
rm 101 bubbler UB	9.42 ug/L	2.27ug/L		
rm 102 bubbler UB	6.10 ug/L	1.79 ug/L		
rm 103 bubbler UB	9.41 ug/L	3.29ug/L		
rm 104 bubbler UB	2.68 ug/L	1.82ug/L		
rm 105 bubbler UB	19.2 ug/L	5.90 ug/L	2.52 ug/L	1.11 UG/L
rm 106 bubbler UB	13.6 ug/L	1.93 ug/L	12.1 ug/L	<1.0 ug/L
rm 107 bubbler UB	6.75 ug/L	1.82 ug/L		
rm 108 bubbler UB	12.3 ug/L	2.35ug/L		
rm 109 bubbler UB	13.6 ug/L	1.25 ug/L		
rm 110 bubbler UB	13.2 ug/L	1.82ug/L		
rm 111 bubbler UB	9.75 ug/L	1.41 ug/L		
rm 112 bubbler UB	11.4 ug/L	3.73ug/L		
rm 113 bubbler UB	13.4 ug/L	2.19ug/L		
rm 114 bubbler UB	11.0 ug/L	2.26ug/L		
rm 115 bubbler UB	9.51 ug/L	2.23ug/L		
rm 116 bubbler UB	3.88 ug/L	2.08ug/L		
health office sink UB	3.08 ug/L	4.62ug/L		
teachers rm sink UB	8.79 ug/L	2.24ug/L		
main lobby bubbler UB	1.92 ug/L	2.45ug/L		
HW bubbler SA UB	12.6 ug/L	1.45ug/L		
HW bubbler 104 UB	5.93 ug/L	1.82ug/L		
HW bubbler 108 UB	4.47 ug/L	4.49ug/L		
HW bubbler 112 UB	7.24 ug/L	6.62ug/L		
HW bubbler GR UB	2.70 ug/L	2.74ug/L		

EPA - DEP ACTION LEVEL 15.5 ug/L

2018 Test Results

MALCOM BELL (UPPER)

40 BALDWIN RD

SAMPLE LOCATION	First Draw	30 second flush
	Lead Level (Pb Final)	Lead Level (Pb Final)
rm 101 bubbler UB	17.6 ug/L	1.94 ug/L
rm 102 bubbler UB	12.4 ug/L	1.71 ug/L
rm 103 bubbler UB	17.8 ug/L	2.9 ug/L
rm 104 bubbler UB	477 ug/L	1240 ug/L
rm 105 bubbler UB	13.3 ug/L	4.56 ug/L
rm 106 bubbler UB	9.54 ug/L	2.1 ug/L
rm 107 bubbler UB	13.6 ug/L	1.18 ug/L
rm 108 bubbler UB	14.7 ug/L	5.31 ug/L
rm 109 bubbler UB	15.2 ug/L	1.09 ug/L
rm 110 bubbler UB	18.4 ug/L	1.36 ug/L
rm 111 bubbler UB	12.8 ug/L	<1.00 ug/L
rm 112 bubbler UB	13.6 ug/L	6.17 ug/L
rm 113 bubbler UB	55.5 ug/L	2.32 ug/L
rm 114 bubbler UB	15.9 ug/L	2.21 ug/L
rm 115 bubbler UB	16.9 ug/L	2.4 ug/L
rm 116 bubbler UB	16.2 ug/L	1.87 ug/L
health office sink UB	12.2 ug/L	4.9 ug/L
teachers rm sink UB	13.5 ug/L	5.36 ug/L
main lobby bubbler UB	<1.00 ug/L	1.22 ug/L
HW bubbler SA UB	4.79 ug/L	2.77 ug/L
HW bubbler 104 UB	5.18 ug/L	2.06 ug/L
HW bubbler 108 UB	6.61 ug/L	4.78 ug/L
HW bubbler 112 UB	5.14 ug/L	5.87 ug/L
HW bubbler GR UB	6.39 ug/L	1.31 ug/L

EPA - DEP ACTION LEVEL 15.5 ug/L

Bell School water bubblers have been all disconnected/turned off.
Drinking water provided through stand alone water coolers.